

EXTERNAL DIMENSIONS & INTERFACES: SN: 900521

A too important preload torque reduces the efficiency and the life expectancy of the gearbox and the rack.

[illegible]

SPECIFIC REMARKS:
* Accepted according the derogation RX

 ZI-BP79 F45210 FERRIERES www.redex.fr	Tel: +33 2 38 94 42 00 Fax: +33 2 38 94 42 99 Email: info@redex.fr	 ZI-BP79 F45210 FERRIERES www.redex.fr	Tel: +33 2 38 94 42 00 Fax: +33 2 38 94 42 99 Email: info@redex.fr
---	---	--	---